
PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission **Bureau of Historic Preservation** Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Par	rcel/Other No.:	183 / 66-00-01627-00-8 Bock 009 Un	nit 050	County:	Montgomery
Municipality:	Whitpain Towns	hip Address:	861 DeKalb Pike		
Historic Name/Other	Name:				
SITE PLAN			РНОТО І	NFORMAT	TON

PHOTO INFORMATION



Number	Description of View	Direction of Camera		
1	House – façade			
2	House – façade			
3				
4				
5				
6				
Photographer N	ame: Robert Wise Date:	1999		
Negative Location	on: Robert Wise Consulting, Station Square 1, Suite 37 N. Valley Road, Paoli PA 19301	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

IDENTIFICATION AND LOCATION

Survey Code:183		-00-01627-00-8 Block Unit #009-051
County: 1. Montgomery	<u>091</u> 2.	
Municipality: 1. Whitpain Tow	nship 2.	
Municipality: 1. Whitpain Tow Address: 861 DeKalb Pike	Historic Name:	
Other Name:		
Owner Name/Address: Frederick W. I	Brouse 861 DeKalb Pike, Center S	Square PA 19422
Owner Category:x_Private Resource Category:x_Building	DistrictSite	StructureObject
Number/Approximate Number of Reso	urces Covered by This Form: 1	
USGS Quad: 1. Lansdale		
UTM A	C.	
References: B.		
HIST	ORIC AND CURRENT FUNCT	TIONS
Historic Function Category:	Subcategory:	
AResidence	Dwelling	
B		
C		
D		
Particular Type: A.		
В		
C		
D		
Current Function Category:	Subcategory:	Code:
ASingle Family Residence	Dwelling	
B		
C		
D		
	PHYSICAL DESCRIPTION	
Architectural Classification:	ASecond Emp	pire
B		
D	Other:	
Exterior Materials: Foundation	Roof	
Wallsstuce	co Walls	
Other	_ ·	
Other	Other	
OtherStructural System: 1 WidthDepth		

HISTORICAL INFORMATION

Year Built: Additions/	Alterations Date	es:caca.	
Basis for Dating: x Documentary	Physical		
Explain: Tax records			•
0.1, 100,1 1 4,000	_		_
Cultural/Ethnic Affiliation: 1Associated Events: 1	2	Associated Individuals: 1	l2.
Associated Events: I.	2	Architects/Engineers: 1	2.
Builders: 1.	_2.		
MAJ	OR BIBLIOGR	APHICAL REFERENCES	
PRE	VIOUS SURVI	EY, DETERMINATIONS	
EVALU	JATION (Surve	y Director/Consultants Only)	
Individual NR Potential: _x_Yes	No Context(s):		
Contributes to Potential District _x_Y			
Classification: Although recognized a (determined eligible for the National R Class II resource.	as a contributing Register), this res	resource in the Center Square source is individually ineligible	e Historic District for Class I and thus is
	TH	REATS	
Threats: _x 1. None 2. Public Deve	elopment 3. Priva	ate Development 4. Neglect	5. Other
Explain:			
DAPIANI.			
	SURVEYOR	INFORMATION	
	SORVETOR		
Surveyor Name/Title: Robert Wise	_ Date:6	5/16/2000	
Project Name: Whitpain Town			
Organization: Robert Wise Cons			(610) 722-5818
Street and No.: Station Square 1, Su	ite 104, 37 Nort	th Valley Road	
City, State: Paoli, Pa)1
Additional Survey Documentation:		-	
Associated Survey Codes:	n/a		

a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission Bureau for Historic Preservation

Survey Code: _	183	Tax Parcel/Other No.: 66-00	-01627-00-8 Block Unit #009-051
		Municipalit	
Address:	861 DeKalb Pike	.	7
Historic/Other	Name:		

PHYSICAL DESCRIPTION:

This house consists of a core with a Mansard roof and some rear additions. The core is a three story, three bay building clad in stucco. The roof is pyramidal and has a flared Mansard on the front and rear. A cornice runs along the juncture of the roof and wall on the sides of the house and forms the junction between the two roof slopes on the front and rear. The two dormers in the Mansard roof have segmental arches. Windows on the second floor have louvered shutters and appear to have been replaced. All of the windows appear to be one over one; there are two windows on the second and third floor facades and two flanking the door on the first floor. One of these first floor windows is a modern nine pane replacement. The door has a large broken pediment which is not original. There are several additions, including one two-story addition clad in stucco with an end chimney. A small frame entry porch has a gabled hood and square columns; the roof of this porch is covered with asphalt shingles.

Classification: Although recognized as a contributing resource in the Center Square Historic District (determined eligible for the National Register), this resource is individually ineligible for Class I and thus is a Class II resource.



