

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 063 / 66-00-04246-00-8 Block 009A Unit 024

County: Montgomery


Municipality: Whitpain Township

Address: Morris Road

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House	
2	Façade (left)	
3	Sheds	
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 063 Tax Parcel/Other No.: 66-00-04246-00-8 Block Unit #009A-024
 County: 1. Montgomery 2. _____
 Municipality: 1. Whitpain Township 2. _____
 Address: 1948 Morris Road Historic Name: _____
 Other Name: _____
 Owner Name/Address: Charles & Gertrude Lake 1970 Morris Rd P.O. Box 1231 N Wales PA 19454
 Owner Category: x Private _____ Public-local _____ Public-state _____ Public-federal _____
 Resource Category: x Building _____ District _____ Site _____ Structure _____ Object _____
 Number/Approximate Number of Resources Covered by This Form: 3
 USGS Quad: 1. Lansdale 2. _____
 UTM A. _____ C. _____
 References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: _____ Subcategory: _____ Code: _____
 A. Residence _____ Dwelling _____
 B. _____
 C. _____
 D. _____

Particular Type: A. _____
 B. _____
 C. _____
 D. _____

Current Function Category: _____ Subcategory: _____ Code: _____
 A. Single Family Residence _____ Dwelling _____
 B. _____
 C. _____
 D. _____

PHYSICAL DESCRIPTION

Architectural Classification: _____
 A. Vernacular _____
 B. _____ C. _____
 D. _____ Other: _____

Exterior Materials: Foundation _____ Roof _____
 Walls Machine Shingles _____ Walls _____
 Other _____ Other _____

Structural System: 1. _____
 Width 3 bay / 30 feet _____ Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ___ ca. ___ Additions/Alterations Dates: ___ ca. ___ ca. ___
Basis for Dating: Documentary ___ Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. ___ 2. ___ Associated Individuals: 1. ___ 2. ___
Associated Events: 1. ___ 2. ___ Architects/Engineers: 1. ___ 2. ___
Builders: 1. ___ 2. ___

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___ Yes No Context(s): _____
Contributes to Potential District ___ Yes ___ No District Name/Status: _____

Classification: Because of the highly altered state of the house, it is a Class II resource.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: _____ n/a
Associated Survey Codes: _____ n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 063 Tax Parcel/Other No.: 66-00-04246-00-8 Block 009A Unit 024
County: Montgomery 091 Municipality: Whitpain Township
Address: 1948 Morris Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

Standing across from 1925 Morris Road is this vernacular farmhouse. The original section, a two story, stucco over stone, gabled roof, vernacular structure is now the rear addition. The main section, fronting Morris Road, is a two story, hipped roof building, probably constructed at the turn of the 19th century. The core has a slate roof whose gable end is fronts Morris Road and the front addition. The main addition is a two story, three bay house with a hipped roof core (front) and a gabled roof rear addition. The siding is machine shingles, the roof is composed of diamond-shaped shingles. Under the eaves are scrolled brackets, and the window lintels have a decorative crown molding. An entry porch is composed of two twin square columns supporting a nicely carved entablature that is broken between the pairs of columns. Combined, the building is approximately 30' x 30'.

Associated Resources:

- (1) **Two Story Outbuilding.** Associated with this house are two out buildings. The first is a two story building with a stucco-covered foundation and a frame upper story. This gabled building has two windows on the side and one in the second story gable.
- (2) **Carriage House.** The second building is a two story carriage house. This building is a gable end frame building sitting on an axis perpendicular to that of the house.

Classification: Because of the highly altered state of the house, it is a Class II resource.



