

**PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET**

Pennsylvania Historic and Museum Commission  
 Bureau of Historic Preservation  
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 036 / 66 00 03011 02 8 Block-Unit #022D-013

County: Montgomery

Municipality: Whitpain Township

Address: 225 Kerry Lane

Historic Name/Other Name: \_\_\_\_\_

**SITE PLAN**

**PHOTO INFORMATION**



Number	Description of View	Direction of Camera
1	House – façade (left)	
2	House – façade (right)	
3	House – rear	
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,  
 37 N. Valley Road, Paoli PA 19301

**PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET**

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

**IDENTIFICATION AND LOCATION**

Survey Code: 036 Tax Parcel/Other No.: 66.00 03011.02.8 Block Unit #022D-013

County: 1. Montgomery 091 2. \_\_\_\_\_

Municipality: 1. Whitpain Township 2. \_\_\_\_\_

Address: 225 Kerry Lane Historic Name: \_\_\_\_\_

Other Name: \_\_\_\_\_

Owner Name/Address: Daniel G. & Janet M. Brouse 225 Kerry Lane Blue Bell PA 19422

Owner Category:  Private  Public-local  Public-state  Public-federal

Resource Category:  Building  District  Site  Structure  Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2. \_\_\_\_\_

UTM A. \_\_\_\_\_ C. \_\_\_\_\_

References: B. \_\_\_\_\_ D. \_\_\_\_\_

**HISTORIC AND CURRENT FUNCTIONS**

**Historic Function Category: Subcategory: Code:**

A. Residence\_1850 2,055 SF Land 0.69 Acre Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Particular Type: A. \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

**Current Function Category: Subcategory: Code:**

A. Single Family Residence Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

**PHYSICAL DESCRIPTION**

Architectural Classification: A. Vernacular \_\_\_\_\_

B. \_\_\_\_\_ C. \_\_\_\_\_

D. \_\_\_\_\_ Other: \_\_\_\_\_

Exterior Materials: Foundation \_\_\_\_\_ Roof asphalt shingles \_\_\_\_\_

Walls stone \_\_\_\_\_ Walls \_\_\_\_\_

Other \_\_\_\_\_ Other \_\_\_\_\_

Structural System: 1. \_\_\_\_\_ 2. \_\_\_\_\_

Width 3 bay \_\_\_\_\_ Depth \_\_\_\_\_ Stories/Height 2.5 \_\_\_\_\_

## HISTORICAL INFORMATION

Year Built: ca. 1850 Additions/Alterations Dates: ca. ca.

Basis for Dating:  Documentary  Physical

Explain: Tax records

Cultural/Ethnic Affiliation: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Associated Individuals: 1. \_\_\_\_\_ 2. \_\_\_\_\_  
Associated Events: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Architects/Engineers: 1. \_\_\_\_\_ 2. \_\_\_\_\_  
Builders: 1. \_\_\_\_\_ 2. \_\_\_\_\_

## MAJOR BIBLIOGRAPHICAL REFERENCES

## PREVIOUS SURVEY, DETERMINATIONS

## EVALUATION (Survey Director/Consultants Only)

Individual NR Potential:  Yes  No Context(s): \_\_\_\_\_

Contributes to Potential District  Yes  No District Name/Status:

**Classification:** This house has been nicely restored, and the summer kitchen is a rare architectural feature. Although the farmland has been developed to the rear of the house, it continues to be a prominent feature along the main road. Class II.

## THREATS

Threats:  1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

## SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000

Project Name: Whitpain Township Historic Resource Survey

Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818

Street and No.: Station Square 1, Suite 104, 37 North Valley Road

City, State: Paoli, Pa Zip Code: 19301

Additional Survey Documentation: n/a

Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM  
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission  
Bureau for Historic Preservation

Survey Code: 036 Tax Parcel/Other No.: 66 00 03011 02 8 Block-Unit #022D-013  
County: Montgomery 091 Municipality: Whitpain Township

Address: 225 Kerry Lane  
Historic/Other Name:

**PHYSICAL DESCRIPTION:**

The oldest units of this house were constructed c. 1850 following vernacular prototypes with three later additions. The core is a two and a half story, three-bay structure with uncoursed stone walls. The roof is end-gabled with asphalt shingles. Each of the two dormers on the core has two windows. Windows are six over six double hung; those second story windows on the façade have shutters. A stone arch over the door crowns an elliptical fanlight.

There are three additions. Attached to the core is a large two and a half story rear addition clad in stucco which shares the roof profile of the core and includes a two-story flat-roofed tower. A single dormer on this addition has two six-pane awnings. The second addition is really the summer kitchen with a large stone chimney and simple drop siding. It is attached to the side of the rear addition and tower. The third addition appears to be a one-story enclosed porch.

**Classification:** This house has been nicely restored, and the summer kitchen is a rare architectural feature. Although the farmland has been developed to the rear of the house, it continues to be a prominent feature along the main road. Class II.



