

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 115 / 66-00-06511-00-2 Block Unit #018-028

County: Montgomery

Municipality: Whitpain Township

Address: 571 Skippack Pike

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 115 Tax Parcel/Other No.: 66-00-06511-00-2 Block Unit #018-028

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 571 Skippack Pike Historic Name:

Other Name:

Owner Name/Address: Jean Zanger & Beverly McCartney 571 Skippack Pk Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C.

References: B. _____ D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Federal _____

B. _____ C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof tin _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 5 _____ Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ___ ca. _____ Additions/Alterations Dates: ___ ca. ___ ca. ___
Basis for Dating: Documentary ___ Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___ Yes No Context(s): _____
Contributes to Potential District ___ Yes ___ No District Name/Status:

Classification: This building, in poor condition, is Class II.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 115 Tax Parcel/Other No.: 66-00-06511-00-2 Block Unit #018-028
County: Montgomery 091 Municipality: Whitpain Township
Address: 571 Skippack Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This 5-bay, Federal style house consists of the main core with two, rear shed additions. The core has 2 stories with stucco over stonewalls. The house has an end gabled, standing seam tin roof. Two small, flush chimneys are located at each end, but they are not original. The walls of the core are patched in several places. The core measures 35'x 20'. The main entrance is in the center and consists of a deeply inset door and transom. The main addition is a 2-story stucco over stone unit that creates an el-shape. In the void of the ell there is another, frame, single story, shed roof addition.

Classification: This building, in poor condition, is Class II.

