

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
 Bureau of Historic Preservation
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 014 / 66 00 01825 00 8 Block-Unit #010-006

County: Montgomery

Municipality: Whitpain Township

Address: 676 DeKalb Pike

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House - façade	
2		
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
 37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 014 Tax Parcel/Other No.: 66 00 01825 00 8 Block Unit #010-006

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 676 DeKalb Pike Historic Name:

Other Name:

Owner Name/Address: Lojoci P.O. Box 151 Center Square PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C.

References: B. _____ D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence 1870 2,942 SF Land 0.45 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Multi Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Victorian _____

B. _____ C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof asphalt shingles _____

Walls stone _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bay / 30 feet Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1870 Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status:

Classification: Class II, due to alterations.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 014 Tax Parcel/Other No.: 66 00 01825 00 8 Block-Unit #010-006
County: Montgomery 091 Municipality: Whitpain Township
Address: 676 DeKalb Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Mansard roofed, Victorian style house has been recently rehabbed and altered. The rehabilitation included the installation of flat-faced rubble stone and new, 1x1 sash windows. In any event, the house has several intact features. The house has 2.3 stories, a full length, flat roofed, front porch, and is 3 bays wide. Prominent features include gabled dormers on the 3 visible sides of the house (as visible from the road), a flared roof, and pediment lintels. The main doorway is centered on the main facade. It consists of a French door, transom, and pediment lenth over the door. The roof is composed of slate-like asphalt. Other features include a single story, bay window on the western side, as well as a 3 level extension towards the rear of the house. There is also a small shed roofed addition on the rear of the house.

Classification: Class II, due to alterations.

676 DeKalb #1



676 DeKalb #2

