

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
 Bureau of Historic Preservation
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 062 / 66 00 04093 00 8 Block-Unit #009A-018 County: Montgomery

Municipality: Whitpain Township Address: 1925 Morris Road

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House	
2		
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
 37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

IDENTIFICATION AND LOCATION

Survey Code: 062 Tax Parcel/Other No.: 66 00 04093 00 8 Block Unit #009A-018
 County: 1. Montgomery 2. _____
 Municipality: 1. Whitpain Township 2. _____
 Address: 1925 Morris Road Historic Name: _____
 Other Name: _____
 Owner Name/Address: FC Haab Co. Inc. 2314 Market Street Philadelphia PA 19103
 Owner Category: x Private _____ Public-local _____ Public-state _____ Public-federal _____
 Resource Category: x Building _____ District _____ Site _____ Structure _____
 Number/Approximate Number of Resources Covered by This Form: 1
 USGS Quad: 1. Lansdale 2. _____
 UTM A. _____ C. _____
 References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: _____ Subcategory: _____ Code: _____
 A. Residence 1870 1,320 SF Land 0.15 Acre Dwelling _____
 B. _____
 C. _____
 D. _____

Particular Type: A. _____
 B. _____
 C. _____
 D. _____

Current Function Category: _____ Subcategory: _____ Code: _____
 A. Single Family Residence Dwelling _____
 B. _____
 C. _____
 D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Vernacular _____
 B. _____ C. _____
 D. _____ Other: _____

Exterior Materials: Foundation _____ Roof asphalt shingles
 Walls _____ Walls _____
 Other _____ Other _____

Structural System: 1. _____ 2. _____
 Width 4 bay _____ Depth _____ Stories/Height 2

HISTORICAL INFORMATION

Year Built: ca. 1870 Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: This well-maintained farmhouse is a Class II resource due to its additions.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: _____ n/a
Associated Survey Codes: _____ n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 062 Tax Parcel/Other No.: 66.00.04093.00.8 Block-Unit #009A-018
County: Montgomery 091 Municipality: Whitpain Township
Address: 1925 Morris Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This building is a well-maintained vernacular farmhouse. The core is a two story and attic, three bay frame house with end gables, which was built c. 1870. The roof is end gabled and has asphalt shingles. Each of the windows has shutters. On the rear of the house is a protruded bay with three sides and a hipped roof. An addition to the core is two stories. Shutters frame each of its windows, and it has an end chimney.

Classification: This well-maintained farmhouse is a Class II resource due to its additions.