

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
 Bureau of Historic Preservation
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 154 / 66-00-06430-00-2 Block Unit #007-003 County: Montgomery

Municipality: Whitpain Township Address: 1950 Skippack Pike

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2		
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
 37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 154 Tax Parcel/Other No.: 66-00-06430-00-2 Block Unit #007-003

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1950 Skippack Pike Historic Name:

Other Name:

Owner Name/Address: Horsham ICDA c/o Gary M. Sherman P.O. Box 328 Tamaqua PA 18252

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C.

References: B. _____ D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Georgian _____

B. _____ C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bays / 30 feet Depth _____ Stories/Height 2

HISTORICAL INFORMATION

Year Built: ___ ca. _____ Additions/Alterations Dates: ___ ca. ___ ca. ___
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___ Yes No Context(s): _____
Contributes to Potential District ___ Yes ___ No District Name/Status:

Classification: Class II due to poor condition and alterations.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 154 Tax Parcel/Other No.: 66-00-06430-00-2 Block Unit #007-003
County: Montgomery 091 Municipality: Whitpain Township
Address: 1950 Skippack Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This 3-bay, 2-story vernacular farmhouse, with Federal style influences, sits abandoned and deteriorating. It consists of the core with a rear addition. Also located on the property is a single story, frame building.

The core is a symmetrical, two-story, end-gabled, three-bay building with a center entrance. The steeply pitched roof is slate. There are small, brick, flush chimneys on both ends of the house. Thick cove molding can be found under the eaves. The walls are stucco over stone. Windows are 2x2 sash. Like many houses in the Township, the attic floor features a twin window arrangement with angled tops under the gables. A portico held up by Tuscan columns protects the front entrance. The core measures 30' x 18'.

A large addition is attached to the rear of the core. It protrudes from the southern end of the core approximately 4 feet. The addition has a flat roof, cornice, and two stories. Like the core, its walls are stucco over stone. Overall, the building measures 34' x 40'.

Classification: Class II due to poor condition and alterations.

